



Gerlach & Schröder GbR  
Nürnberger Str. 34  
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202401-24707

If you have any questions, please state the report number and date

Date: 02.01.2024

## Report

|                                      |                                                                         |
|--------------------------------------|-------------------------------------------------------------------------|
| <b>Subject</b>                       | Report                                                                  |
| <b>Inspection date/location</b>      | 02.01.2024   Dick Automobile e.K., Ernst-Abbe-Str. 2,<br>DE-36179 Bebra |
| <b>Client</b>                        | Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra                |
| <b>Registration number</b>           | GI-NG 400                                                               |
| <b>Vehicle Identification Number</b> | WDD1770121J140588                                                       |

REPORTNUMBER: 202401-24707

If you have any questions, please state the report number and date

Date: 02.01.2024

## Report

|                                      |                                                                                        |
|--------------------------------------|----------------------------------------------------------------------------------------|
| <b>Subject</b>                       | Report                                                                                 |
| <b>Client</b>                        | Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra                               |
| <b>Inspection date/location</b>      | 02.01.2024   Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra                   |
| <b>Registration number</b>           | GI-NG 400                                                                              |
| <b>Vehicle type</b>                  | Estate Car                                                                             |
| <b>Manufacturer</b>                  | Mercedes-Benz                                                                          |
| <b>Model / Sales description</b>     | A 200d AMG Line 110 Aut.5d                                                             |
| <b>Key numbers HSN/TSN</b>           | /                                                                                      |
| <b>Vehicle identification number</b> | WDD1770121J140588                                                                      |
| <b>Previous owners</b>               | 1                                                                                      |
| <b>First registration</b>            | 10.10.2019                                                                             |
| <b>Mileage</b>                       | 86.602 km                                                                              |
| <b>Colour / Colour Code</b>          | BLAU                                                                                   |
| <b>Fuel Type</b>                     | Diesel                                                                                 |
| <b>Cubic Capacity / Power</b>        | 1.950 cm <sup>3</sup> / 110 kW                                                         |
| <b>Number of doors / seats</b>       | 5 / 5                                                                                  |
| <b>Transmission</b>                  | Automatic transmission                                                                 |
| <b>Number of keys</b>                | 1                                                                                      |
| <b>Last maintenance</b>              | 07.10.2022 / 64.568 km                                                                 |
| <b>Next vehicle inspection</b>       | 30.10.2024                                                                             |
| <b>Service documentation</b>         | Available                                                                              |
| <b>Trailer coupling</b>              | No                                                                                     |
| <b>Rain sensor</b>                   | Available                                                                              |
| <b>Operating manual</b>              | Available                                                                              |
| <b>Repainting</b>                    | Found<br>Plastic parts could not be evaluated by means of paint thickness measurement. |
| <b>Inspection Condition</b>          | non-dismantled, roadworthy, traffic safe                                               |

REPORTNUMBER: 202401-24707

If you have any questions, please state the report number and date

Date: 02.01.2024

### Tires / Rims

| Axis / Size              | Tires                        | Profile [mm] |
|--------------------------|------------------------------|--------------|
| #1 225/45 R18 front axle | Summer tyre on Aluminium rim | 2/2          |
| #2 225/45 R18 rear axle  |                              | 5/5          |

The state of the tyres is roadworthy.

### Brakes

|        | Front axle | Rear axle |
|--------|------------|-----------|
| Lining | adequate   | adequate  |
| Disc   | adequate   | adequate  |

### Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

| Nr. | Component        | Damage     | Severity | Comment |
|-----|------------------|------------|----------|---------|
| 1   | Bumper front     |            | Medium   |         |
| 2   | Bonnet           |            | Slight   |         |
| 3   | Windshield       |            | Severe   |         |
| 4   | Roof             | Scratch    | Slight   |         |
| 5   | Aluminium rim FL |            | Slight   |         |
| 6   | Door FL          |            | Slight   |         |
| 7   |                  |            | Severe   |         |
| 8   | Seat FL          |            | Slight   |         |
| 9   | Side panel left  | Stone chip | Slight   |         |
| 10  | Aluminium rim RL |            | Medium   |         |
| 11  | Aluminium rim FR |            | Medium   |         |
| 12  | Fender ri        | Scratch    | Medium   |         |

REPORTNUMBER: 202401-24707

If you have any questions, please state the report number and date

Date: 02.01.2024

|    |                  |        |
|----|------------------|--------|
| 13 | Aluminium rim RR | Medium |
| 14 | Tailgate panel   | Slight |

## Previous damages / Repaintings

The vehicle was found to have been properly and professionally repaired.

Essentially, the following vehicle parts were replaced or repaired:

- Bumper fr.;
- Bumper re.;

A sample-like paint thickness measurement showed an increased paint thickness, which is almost certainly due to a repaired damage.

## Test drive / Inspection

There was a short drive on the company site.

A test run of the engine was carried out.

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

## Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 02.01.2024



---

Nico Emme

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

**Attached:** 17 overview pictures, 15 damage pictures

REPORTNUMBER: 202401-24707

If you have any questions, please state the report number and date

Date: 02.01.2024

## Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202401-24707

If you have any questions, please state the report number and date

Date: 02.01.2024



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12

REPORTNUMBER: 202401-24707

If you have any questions, please state the report number and date

Date: 02.01.2024



Image 13



Image 14



Image 15



Image 16




Image 17

REPORTNUMBER: 202401-24707

If you have any questions, please state the report number and date

Date: 02.01.2024

## Damage pictures



Image 1: Siehe Pos.1



Image 2: Siehe Pos.1



Image 3: Siehe Pos.2



Image 4: Siehe Pos.3




Image 5: Siehe Pos.4



Image 6: Siehe Pos.5



REPORTNUMBER: 202401-24707

If you have any questions, please state the report number and date

Date: 02.01.2024



Image 7: Siehe Pos.6



Image 8: Siehe Pos.7



Image 9: Siehe Pos.8



Image 10: Siehe Pos.9



Image 11: Siehe Pos.10



Image 12: Siehe Pos.11

REPORTNUMBER: 202401-24707

If you have any questions, please state the report number and date

Date: 02.01.2024



Image 13: Siehe Pos.12



Image 14: Siehe Pos.13



Image 15: Siehe Pos.14