



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202403-25557

If you have any questions, please state the report number and date

Date: 15.03.2024

Report

Subject	Report
Inspection date/location	15.03.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	ERB-DC 47
Vehicle Identification Number	WF0FXXWPCFJP20510



REPORTNUMBER: 202403-25557

If you have any questions, please state the report number and date

Date: 15.03.2024

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	15.03.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	ERB-DC 47
Vehicle type	Estate Car
Manufacturer	Ford
Model / Sales description	Mon.Tur.2.0TDCi S&S ST-L.132 A
Key numbers HSN/TSN	8566 / BJE
Vehicle identification number	WF0FXXWPCFJP20510
Previous owners	2
First registration	21.09.2018
Mileage	147.645 km
Colour / Colour Code	
Fuel Type	Diesel
Cubic Capacity / Power	1.997 cm ³ / 132 kW
Number of doors / seats	5 / 5
Transmission	Automatic transmission
Number of keys	2
Last maintenance	25.04.2022 / 119.044 km
Next vehicle inspection	01.09.2025
Service documentation	Available
Trailer coupling	Swiveling
Rain sensor	Available
Operating manual	Available
Repainting	Found Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe



REPORTNUMBER: 202403-25557

If you have any questions, please state the report number and date

Date: 15.03.2024

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 235/45 R18 front axle	Summer tyre on Aluminium rim	5/5
#2 235/45 R18 rear axle		5/5

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	adequate	adequate
Disc	adequate	adequate

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Windshield	Stone chip	Slight	
2	Bonnet	Stone chip	Slight	
3	Bumper front	Stone chip	Slight	
4	Bumper front	Scratch	Slight	
5	Mirror cap left	Stone chip	Slight	
6	Door FL	Scratch	Slight	
7	Door RL	Scratch	Slight	
8	Bumper rear	Scratch	Slight	
9	Tailgate	Scratch	Slight	
10	Mirror cap right	Stone chip	Slight	
11	Fender ri	Stone chip	Slight	

REPORTNUMBER: 202403-25557

If you have any questions, please state the report number and date

Date: 15.03.2024

Previous damages / Repaintings

The vehicle was found to have been properly and professionally repaired.

Essentially, the following vehicle parts were replaced or repaired:

- Engine bonnet; ~ 450µm
- Fender le; ~ 260µm

A sample-like paint thickness measurement showed an increased paint thickness, which is almost certainly due to a repaired damage.

Test drive / Inspection

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 15.03.2024



Daniel Gawlik

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 15 overview pictures, 11 damage pictures

REPORTNUMBER: 202403-25557

If you have any questions, please state the report number and date

Date: 15.03.2024

Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202403-25557

If you have any questions, please state the report number and date

Date: 15.03.2024



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12

REPORTNUMBER: 202403-25557

If you have any questions, please state the report number and date

Date: 15.03.2024



Image 13



Image 14




Image 15

Damage pictures



Image 1: Siehe Pos.1



Image 2: Siehe Pos.2

REPORTNUMBER: 202403-25557

If you have any questions, please state the report number and date

Date: 15.03.2024



Image 3: Siehe Pos.3



Image 4: Siehe Pos.4



Image 5: Siehe Pos.5




Image 6: Siehe Pos.6



Image 7: Siehe Pos.7



Image 8: Siehe Pos.8

REPORTNUMBER: 202403-25557

If you have any questions, please state the report number and date

Date: 15.03.2024



Image 9: Siehe Pos.9



Image 10: Siehe Pos.10



Image 11: Siehe Pos.11