

Gerlach & Schröder GbR Nürnberger Str. 34 DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202405-26234

If you have any questions, please state the report number and date

Date: 10.05.2024

# <u>Report</u>

Subject Inspection date/location

Client Registration number Vehicle Identification Number Report 08.05.2024 | Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra H-OY745 WBAUJ11000LG47726



Gerlach & Schröder GbR Nürnberger Str. 34 DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202405-26234 If you have any questions, please state the report number and date

Date: 10.05.2024

# Report

Subject Client Inspection date/location **Registration number** Vehicle type Manufacturer Model / Sales description Key numbers HSN/TSN Vehicle identification number **Previous owners First registration** Mileage **Colour / Colour Code** Fuel Type **Cubic Capacity / Power** Number of doors / seats Transmission Number of kevs Last maintenance Next vehicle inspection Service documentation **Trailer coupling Rain sensor Operating manual** Repainting

Report Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra 08.05.2024 | Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra H-OY745 Saloon **BMW** X4 xDrive 20i xLine 0005 / CSG WBAUJ11000LG47726 1 03.07.2019 91.088 km grau Petrol 1.998 cm<sup>3</sup> / 135 kW 5/5Automatic transmission 1 06.12.2023 / 87.590 km 01.03.2025 Available No Available Available Not Found Plastic parts could not be evaluated by means of paint thickness measurement. non-dismantled, roadworthy, traffic safe

**Inspection Condition** 



If you have any questions, please state the report number and date

Date: 10.05.2024

### Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 245/50 R19 front axle #2 245/50 R19 rear axle	Summer tyre on Aluminium rim	5/5 6/6

The state of the tyres is roadworthy.

### Brakes

	Front axle	Rear axle
Lining	adequate	adequate
Disc	adequate	adequate

### Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1		Stone chip	Slight	
2	Bumper front	Stone chip	Slight	
3	Door RR	Scratch	Slight	
4	Side panel right	Scratch	Slight	
5	Tailgate	Scratch	Slight	
6	Bumper rear	Scratch	Slight	
7	Door entry RL	Scratch	Slight	
8	Door RL	Scratch	Slight	
9	Door FL	Scratch	Slight	



If you have any questions, please state the report number and date

Date: 10.05.2024

# Previous damages / Repaintings

As far as without further investigations recognizable, at the inspection **no repaired previous damages are detectable.** A random paint thickness measurement showed no abnormalities.

Plastic parts could not be evaluated by means of paint thickness measurement. Thus pre-damages, repaintings or repairs can not be ruled out.

### **Test drive / Inspection**

There was a short drive on the company site.

A test run of the engine was carried out.

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

# **Other information**

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 10.05.2024

Imme

Nico Emme

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 14 overview pictures, 9 damage pictures



If you have any questions, please state the report number and date

Gerlach & Schröder GbR Nürnberger Str. 34 DE-36199 Rotenburg a.d. Fulda/Lisp.

Date: 10.05.2024

# **Overview pictures**



Image 1



Image 3



Image 5



Image 2



Image 4



Image 6



If you have any questions, please state the report number and date

Gerlach & Schröder GbR Nürnberger Str. 34 DE-36199 Rotenburg a.d. Fulda/Lisp.

Date: 10.05.2024





Image 7



<image>

Image 9



Image 11



Image 12





If you have any questions, please state the report number and date

Date: 10.05.2024



	OK 05.10.2021 50.135 km	<b>BMW</b> 25742
,	OK 16.11.2021 53.125 km	BMW 25742
<	OK 25.04.2022 59.056 km	BMW 33213
	OK 06.12.2023 87.590 km	BMW 00863

Image 14

# **Damage pictures**



Image 1: siehe pos.1



Image 3: siehe pos.3



Image 2: siehe pos.2



Image 4: siehe pos.4



If you have any questions, please state the report number and date

Gerlach & Schröder GbR Nürnberger Str. 34 DE-36199 Rotenburg a.d. Fulda/Lisp.

Date: 10.05.2024




Image 5: siehe pos.5



Image 7: siehe pos.7



Image 9: siehe pos.9



Image 6: siehe pos.6



Image 8: siehe pos.8