



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202403-25535

If you have any questions, please state the report number and date

Date: 14.03.2024

Report

Subject	Report
Inspection date/location	14.03.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	F-HR 500
Vehicle Identification Number	W1K1186141N122569



REPORTNUMBER: 202403-25535

If you have any questions, please state the report number and date

Date: 14.03.2024

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	14.03.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	F-HR 500
Vehicle type	Estate Car
Manufacturer	Mercedes-Benz
Model / Sales description	CLA SB 220d AMG Line 140 Aut.
Key numbers HSN/TSN	2222 / AGT
Vehicle identification number	W1K1186141N122569
Previous owners	1
First registration	17.04.2020
Mileage	114.112 km
Colour / Colour Code	WEISS
Fuel Type	Diesel
Cubic Capacity / Power	1.950 cm ³ / 140 kW
Number of doors / seats	5 / 5
Transmission	Automatic transmission
Number of keys	1
Last maintenance	21.09.2023 / 104.657 km
Next vehicle inspection	01.06.2025
Service documentation	Available
Trailer coupling	No
Rain sensor	Available
Operating manual	Available
Repainting	Not Found Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe



REPORTNUMBER: 202403-25535

If you have any questions, please state the report number and date

Date: 14.03.2024

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 225/45 R18 front axle	Summer tyre on Aluminium rim	4/3
#2 225/45 R18 rear axle		4/4

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	adequate	adequate
Disc	adequate	adequate

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Aluminium rim FR	Scratch	Medium	
2	Windshield	Crack	Severe	
3	Bonnet	Scratch	Severe	
4	Bumper front	Stone chip	Slight	
5	Door FL	Scratch	Slight	
6	Bumper rear	Scratch	Severe	
7	Door RR	Scratch	Slight	
8	Door entry RR	Scratch	Slight	
9	Door FR	Scratch	Slight	
10	Fender ri	Stone chip	Slight	

REPORTNUMBER: 202403-25535

If you have any questions, please state the report number and date

Date: 14.03.2024

Previous damages / Repaintings

As far as without further investigations recognizable, at the inspection **no repaired previous damages are detectable**. A random paint thickness measurement showed no abnormalities.

Plastic parts could not be evaluated by means of paint thickness measurement. Thus pre-damages, repaintings or repairs can not be ruled out.

Test drive / Inspection

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 14.03.2024



Daniel Gawlik

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 16 overview pictures, 11 damage pictures

REPORTNUMBER: 202403-25535

If you have any questions, please state the report number and date

Date: 14.03.2024

Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202403-25535

If you have any questions, please state the report number and date

Date: 14.03.2024



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12

REPORTNUMBER: 202403-25535

If you have any questions, please state the report number and date

Date: 14.03.2024



Image 13



Image 14



Image 15



Image 16

Damage pictures



Image 1: Siehe Pos.1



Image 2: Siehe Pos.2

REPORTNUMBER: 202403-25535

If you have any questions, please state the report number and date

Date: 14.03.2024



Image 3: Siehe Pos.3



Image 4: Siehe Pos.4



Image 5: Siehe Pos.4



Image 6: Siehe Pos.5



Image 7: Siehe Pos.6



Image 8: Siehe Pos.7

REPORTNUMBER: 202403-25535

If you have any questions, please state the report number and date

Date: 14.03.2024



Image 9: Siehe Pos.8



Image 10: Siehe Pos.9



Image 11: Siehe Pos.10