



Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202410-27847

If you have any questions, please state the report number and date

Date: 05.10.2024

Report

Subject	Report
Inspection date/location	05.10.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	M-HZ 4471 E
Vehicle Identification Number	LSJA24396MN137659



REPORTNUMBER: 202410-27847

If you have any questions, please state the report number and date

Date: 05.10.2024

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	05.10.2024 Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	M-HZ 4471 E
Vehicle type	Saloon
Manufacturer	MG
Model / Sales description	EHS PHEV Luxury
Key numbers HSN/TSN	/
Vehicle identification number	LSJA24396MN137659
Previous owners	1
First registration	31.05.2022
Mileage	36.873 km
Colour / Colour Code	WEISS
Fuel Type	Hybrid/Petrol
Cubic Capacity / Power	1.490 cm ³ / 119 kW
Number of doors / seats	5 / 5
Transmission	Automatic transmission
Number of keys	1
Last maintenance	28.06.2023 / 7.394 km
Next vehicle inspection	01.06.2024
Service documentation	Service history incomplete (Vom Ölzettel abgelesen)
Trailer coupling	No
Rain sensor	Available
Operating manual	Available
Repainting	Found Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe



REPORTNUMBER: 202410-27847

If you have any questions, please state the report number and date

Date: 05.10.2024

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 235/50 R18 front axle	All-season tyre on Aluminium rim	4/4
#2 235/50 R18 rear axle		6/6

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	adequate	adequate
Disc	adequate	adequate

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Bonnet		Slight	
2	Roof	Stone chip	Slight	
3	Mirror cap left		Slight	
4	Centre console	Scratch	Medium	
5	Door RL		Slight	
6			Severe	
7	Aluminium rim FR		Slight	
8			Severe	
9	Bumper rear		Medium	

REPORTNUMBER: 202410-27847

If you have any questions, please state the report number and date

Date: 05.10.2024

Previous damages / Repaintings

The vehicle was found to have been properly and professionally repaired.

Essentially, the following vehicle parts were replaced or repaired:

- Bumper fr.;

A sample-like paint thickness measurement showed an increased paint thickness, which is almost certainly due to a repaired damage.

Test drive / Inspection

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 05.10.2024



Daniel Gawlik

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 18 overview pictures, 9 damage pictures

REPORTNUMBER: 202410-27847

If you have any questions, please state the report number and date

Date: 05.10.2024

Overview pictures



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6

REPORTNUMBER: 202410-27847

If you have any questions, please state the report number and date

Date: 05.10.2024



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12

REPORTNUMBER: 202410-27847

If you have any questions, please state the report number and date

Date: 05.10.2024



Image 13



Image 14



Image 15



Image 16



Image 17




Image 18

REPORTNUMBER: 202410-27847

If you have any questions, please state the report number and date

Date: 05.10.2024

Damage pictures



Image 1: Siehe Pos.1



Image 2: Siehe Pos.2



Image 3: Siehe Pos.3



Image 4: Siehe Pos.4



Image 5: Siehe Pos.5



Image 6: Siehe Pos.6

REPORTNUMBER: 202410-27847

If you have any questions, please state the report number and date

Date: 05.10.2024



Image 7: Siehe Pos.7



Image 8: Siehe Pos.8



Image 9: Siehe Pos.9