

Date: 07.05.2024

REPORTNUMBER: 202405-25949

If you have any questions, please state the report number and date

Report

Subject Report

Inspection date/location 16.04.2024 | Dick Automobile e.K., Ernst-Abbe-Str. 2,

DE-36179 Bebra

Client Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra

Registration number FT-J1042

Vehicle Identification Number WBAUZ35010NE17941

07.05.2024 VIN: WBAUZ35010NE17941; Report number: 202405-25949 Page 1 of 8



Date: 07.05.2024

REPORTNUMBER: 202405-25949

If you have any questions, please state the report number and date

Report

Subject Report

Client Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra Inspection date/location 16.04.2024 | Dick Automobile e.K., Ernst-Abbe-Str. 2,

DE-36179 Bebra

Registration numberFT-J1042Vehicle typeEstate CarManufacturerBMW

Model / Sales descriptionX3 xDrive 20dKey numbers HSN/TSN0005 / CRW

Vehicle identification number WBAUZ35010NE17941

Previous owners 1

First registration 23.10.2019 **Mileage** 142.484 km

Colour / Colour Code blau **Fuel Type** Diesel

Cubic Capacity / Power 1.995 cm³ / 140 kW

Number of doors / seats 5 / 5

Transmission Automatic transmission

Number of keys 2

Last maintenance 05.01.2024 / 136.323 km

Next vehicle inspection01.10.2024Service documentationAvailableTrailer couplingSwivelingRain sensorAvailableOperating manualAvailableRepaintingNot Found

Plastic parts could not be evaluated by means of paint

thickness measurement.

Inspection Condition non-dismantled, roadworthy, traffic safe

07.05.2024 VIN: WBAUZ35010NE17941; Report number: 202405-25949 Page 2 of 8

REPORTNUMBER: 202405-25949

If you have any questions, please state the report number and date Date: 07.05.2024

Tires / Rims

Axis / Size	Tires	Profile [mm]
#1 225/60 R18 front axle	Summer tyre on Aluminium rim	4/4
#2 225/60 R18 rear axle		5/5

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	adequate	adequate
Disc	adequate	adequate

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Bonnet	Stone chip	Slight	
2	Bumper front	Stone chip	Slight	
3	Door FR	Scratch	Slight	
4	Door entry RR	Scratch	Slight	
5	Door RR	Scratch	Slight	
6	Bumper rear	Scratch	Slight	
7	Tailgate panel	Scratch	Slight	
8	Door entry RL	Scratch	Slight	

Previous damages / Repaintings

As far as without further investigations recognizable, at the inspection **no repaired previous damages are detectable.** A random paint thickness measurement showed no abnormalities.

Plastic parts could not be evaluated by means of paint thickness measurement. Thus

07.05.2024 VIN: WBAUZ35010NE17941; Report number: 202405-25949 Page 3 of 8

Date: 07.05.2024

REPORTNUMBER: 202405-25949

If you have any questions, please state the report number and date

pre-damages, repaintings or repairs can not be ruled out.

Test drive / Inspection

There was a short drive on the company site.

A test run of the engine was carried out.

At the time of the inspection the vehicle was not authorized for public roads.

An impairment of traffic safety was not detected.

The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

1/ Enne

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 07.05.2024

Nico Emme

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 15 overview pictures, 8 damage pictures

07.05.2024 VIN: WBAUZ35010NE17941; Report number: 202405-25949 Page 4 of 8

Date: 07.05.2024

REPORTNUMBER: 202405-25949

If you have any questions, please state the report number and date

Overview pictures



Image 1



Image 3



Image 5



Image 2



Image 4



Image 6

07.05.2024 VIN: WBAUZ35010NE17941; Report number: 202405-25949 Page 5 of 8

Date: 07.05.2024

REPORTNUMBER: 202405-25949

If you have any questions, please state the report number and date



Image 7



Image 9



Image 11



Image 8



Image 10



Image 12

07.05.2024 VIN: WBAUZ35010NE17941; Report number: 202405-25949 Page 6 of 8

Date: 07.05.2024

REPORTNUMBER: 202405-25949

If you have any questions, please state the report number and date



Image 13



Image 15



Image 14

Damage pictures



Image 1: siehe pos.1



Image 2: siehe pos.2

07.05.2024 VIN: WBAUZ35010NE17941; Report number: 202405-25949 Page 7 of 8

Date: 07.05.2024

REPORTNUMBER: 202405-25949

If you have any questions, please state the report number and date



Image 3: siehe pos.3



Image 5: siehe pos.5



Image 7: siehe pos.7



Image 4: siehe pos.4




Image 6: siehe pos.6



Image 8: siehe pos.8

07.05.2024 VIN: WBAUZ35010NE17941; Report number: 202405-25949 Page 8 of 8