Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202603-32863

If you have any questions, please state the report number and date

Date: 10.03.2026

Report

Subject	Report
Inspection date/location	10.03.2026 | Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Registration number	FZ-RZ 8
Vehicle Identification Number	WDD2210951A371325

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202603-32863
If you have any questions, please state the report number and date

Date: 10.03.2026

Report

Subject	Report
Client	Dick Automobile e.K., Otto-Hahn-Str. 4-6, DE-36179 Bebra
Inspection date/location	10.03.2026 | Dick Automobile e.K., Ernst-Abbe-Str. 2, DE-36179 Bebra
Registration number	FZ-RZ 8
Vehicle type	Saloon
Manufacturer	Mercedes-Benz
Model / Sales description	S 400
Key numbers HSN/TSN	1313 / BHD
Vehicle identification number	WDD2210951A371325
Previous owners	
First registration	13.10.2010
Mileage	120.478 km
Colour / Colour Code	SILBER
Fuel Type	Hybrid/Petrol
Cubic Capacity / Power	3.498 cm³ / 205 kW
Number of doors / seats	5 / 5
Transmission	Automatic transmission
Number of keys	2
Last maintenance	27.08.2025 / 105.005 km
Next vehicle inspection	01.10.2027
Service documentation	Nonexistent
Trailer coupling	No
Rain sensor	Available
Operating manual	Available
Repainting	Found Plastic parts could not be evaluated by means of paint thickness measurement.
Inspection Condition	non-dismantled, roadworthy, traffic safe

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202603-32863
If you have any questions, please state the report number and date

Date: 10.03.2026

Tires / Rims

Axis / Size		Tires	Profile [mm]
#1 235/55 R17	front axle	Winter tyre on Aluminium rim	7/7
#2 235/55 R17	rear axle		6/6

The state of the tyres is roadworthy.

Brakes

	Front axle	Rear axle
Lining	good	adequate
Disc	good	good

Value decreasing factors / signs of usage

The report determines only damages and faults that exceed the normal wear and tear of the vehicle corresponding to the running time / mileage or if specific values are below the usual wear measurement.

Nr.	Component	Damage	Severity	Comment
1	Bonnet	Stone chip	Slight	
2	Bumper front	Stone chip	Slight	
3	Bumper front	Scratch	Slight	
4	Aluminium rim FR	Scratch	Medium	
5	Side panel left	Scratch	Slight	

Previous damages / Repaintings

The vehicle was found to have been properly and professionally repaired.

Essentially, the following vehicle parts were replaced or repaired:

- Fender ri.; ~ 200µm
- Door f.r.; ~ 170µm

A sample-like paint thickness measurement showed an increased paint thickness, which is almost certainly due to a repaired damage.

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202603-32863
If you have any questions, please state the report number and date

Date: 10.03.2026

Test drive / Inspection

There was a short drive on the company site.
A test run of the engine was carried out.
At the time of the inspection the vehicle was not authorized for public roads.
An impairment of traffic safety was not detected.
The inspection included an external inspection of the vehicle without the dismantling of trim parts etc.

Other information

The inspection conditions were sufficient for the investigation of the vehicle.

Bebra 10.03.2026

Nico Emme

This printed copy was produced electronically. The appointed expert assures that the content correctly reflects the statements made by him. It is valid without an original signature.

Attached: 16 overview pictures, 5 damage pictures

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202603-32863

If you have any questions, please state the report number and date

Date: 10.03.2026

Overview pictures

Image 1

Image 2

Image 3

Image 4

Image 5

Image 6

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202603-32863

If you have any questions, please state the report number and date

Date: 10.03.2026

Image 7

Image 8

Image 9

Image 10

Image 11

Image 12

KÜS INGENIEURBÜRO für Kfz-Wesen
GERLACH & SCHRÖDER
LISPENHAUSEN

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202603-32863

If you have any questions, please state the report number and date

Date: 10.03.2026

Image 13

Image 14

Image 15

Image 16

Damage pictures

Image 1:

Image 2:

Gerlach & Schröder GbR
Nürnberger Str. 34
DE-36199 Rotenburg a.d. Fulda/Lisp.

REPORTNUMBER: 202603-32863

If you have any questions, please state the report number and date

Date: 10.03.2026

Image 3:

Image 4:

Image 5: